

WAGNER



STEAMFORCE PRO
USER GUIDE
ORIGINAL-BETRIEBSANLEITUNG



16. Correction of Malfunctions

Malfunction	Cause	Remedy
Unit fails to boil	<ul style="list-style-type: none"> • The thermal cut-out has operated • Usage of an extension lead 	Switch off, allow to cool, refill with water then switch on again Check that the thermal reset button has not tripped out. Check that the extension lead is rated at minimum of 15 Amps (EU)/ 13 Amps (UK) - 230V unit only and fully unwound.
Unit keeps cutting out	<ul style="list-style-type: none"> • Water is below MIN level • Usage of an extension lead • Additives have been used 	Refill water See above Refresh water
Steam escaping from pressure cap	<ul style="list-style-type: none"> • Blockage in hose or steamplate • Build up around cap area 	Remove blockage Clean seating around cap area



If the unit still will not operate return the unit to the dealer or authorised agent for investigation.

17. Technical Data

Power source:	220-240 V ~ 50Hz	Power consumption:	2750W
Steaming time:	80-100 Minutes	Hose length:	5 m
Boiler capacity:	7.5L	Unit weight:	9.4kg
Max persons:	1	Max standing weight:	127kg

18. Accessories

Further information about the WAGNER range of products for decorative preparation is available on www.wagner-group.com.